

Batheaston-Highway Concerns	Location	Plan point	Issue raised	Action Required	Complete/Outstanding
Traffic Management	Bannerdown	2	Install pavement at bottom of road - Bannerdown	Not Viable to pursue, restricted road width unable to install pavement.	Complete
	Bannerdown	4	Raise setts at Barnfield Way Mini-roundabout	Not Viable to pursue, could see damage to cars as its not practise to have raised setts on mini roundabouts where traffic may travel over and damage underside of vehicles	Complete
	Bannerdown	6	Provide pavement from Barnfield Way to High Bannerdown	To be investigated	Site Visit booked for 29th Jan
	Bannerdown	7	Consider pushing out High Bannerdown roadway - to improve sight lines	Carried out work previously to improve sight lines.	Complete
	London Road East	12	Improve Signage at Bathford roundabout to discourage HGV traffic turning left.	Signage installation carried out by Atkins	Complete
	London Road East	13	Similar signage improvement requested at the A46/A4 roundabout to discourage HGV Traffic from turning left to Batheaston and over committing	To be investigated	Site Visit booked for 29th Jan
	Northend	18	Install Sign at the end of Solsbury Lane next to A46 to Stop HGV Traffic turning into Narrow Lane	To be investigated	Site Visit booked for 29th Jan
	Highways	Northend	21	Patching repair has failed on Hollies Lane	George Bottin investigating
London Road East		16	Horizontal section of footpath BA 2/49 to west view road is muddy and resurfacing required	Graeme Stark investigating	This is included in the 2014/15 Capital Programme. The works order has been passed to our contractor and they have been asked to complete the works as a priority. The PROW Team will inform the parish council when the works are complete.
Fosse Lane		8	Gulley collapsing above Eden Park Drive Passage	George Bottin investigating	There are no gullies in the vicinity of this junction however on the assumption that the ditch is what being referred to it is on this years programme of works for this ditch to be maintained.
Bannerdown		5	Replace missing tarmac in road just above Barnfield Way	George Bottin investigating	We have investigated this and found that it is in fact an over-run area and vehicles are driving over a soft verge which is causing a rut to develop. We do not believe that there is any missing tarmac which needs replacing.
Street Lighting	Estate	10	Request for additional street light on Muddy Lane. Promised to be included in 2014 capital monies	Email dated 25/03/2013 did not promise funding but would consider it for the year 2014/15 comparing this with other requests received over the past year.	Scheme to be prioritised and will be constructed subject to sufficient funds being made available.
Parking	Estate	9	Address all Parking problems separately identified - in particular the redundant DYL As agreed with Chris Major and DB	Kris Gardom, newly appointed Parking Engineer investigating	The proposal requested by Batheaston Parish Council to remove some sections of redundant No Waiting At Any Time markings on Catherine Way are within the next Outer Area TRO, which is due to be processed sometime next year.
	Northend	17	Complete Parking Lines improvements e.g. removal of lines in School Lane	Kris Gardom investigating	Atkins have tried to remove the short section of No Waiting At Any Time markings on School Lane, which was agreed through consultation and approved in the last Outer Area TRO, but every time they have been to site a vehicle has been parked on the markings. I will ask them to try one more time and if a vehicle is there again I will speak with parking services about having cones placed on site and have the vehicle issued with a ticket
Engineering Design	Bannerdown	1	Install 20mph Bannerdown	Simon Thomas progressing	Formal consultation complete TRO to be advertised at the end of the month.
	London Road East	11	London Road East Investigate 20mph limits in this area	Simon Thomas progressing	To be investigated.
	London Road East	15	Improvements required to Pavement in front of shops B&NES has capital monies @ 40k and a meeting with K Packer set for 10th Dec	Kelvin Packer investigating	Progressing
Public ROW	Northend	19	Stiles and signs to be installed after footpath BA 2/53 has been reinstated	Graeme Stark investigating	The Definitive Map Modification Order has been confirmed by the Secretary of State and the footpath is now formally recorded on the Definitive Map and Statement. This concludes the case.
	Northend	20	A new footpath BA2/54 is proposed and the planning inspectorate will consider next April 2014	Graeme Stark investigating	The Definitive Map Modification Order has been confirmed by the Secretary of State and the confirmation is currently being advertised. Once the advertising period has ended, and assuming there is no high court challenge, the PROW Team will take the necessary action to have the obstructions and signage on the footpath removed.
Public Transport	Bannerdown	3	Install new bus stop for Colerne-bound buses	Andy Strong investigating	Please contact the Public Transport Team on 01225 394 201 for an update.
	London Road East	14	Bus stop improvements promised at the Stambidge Stop- with bollards	Andy Strong investigating	Please contact the Public Transport Team on 01225 394 201 for an update.